

Instructions: Glass Polishing Kit


Warm
Glass

Your kit contains:

- 100g x Cerium Oxide Polishing Powder
- 1 x Mandrel
- 2 x Large Polishing Discs (25mm)
- 2 x Small Polishing Discs (15mm)
- 3 x Pointed Polishing Tips (19mm length)

Instructions:

1. Attach the mandrel to the Dremel rotary tool and screw on your polishing disc or polishing tip.
2. Mix a small amount of the powder and water to make a milk-like mixture. Then apply thinly to the polishing disc or glass.
3. On a medium speed, move the polishing head over the glass. Keep the head moving as holding it in the same spot will cause friction heat which can cause glass to crack.
4. Apply more cerium oxide mixture as needed.



Please note: Polishing is the last stage in coldworking. Surfaces will not polish unless they have been finished to a minimum of 1800 grit before the cerium oxide is used to produce a high gloss finish.

Looking for Tips & Advice?

Visit the Knowledge Base on our website for a wealth of information:

www.warm-glass.co.uk